Approved For Release 2009/09/01: CIA-RDP78-03097A000200010263-3



TO

Chief Engineer, Rosein

This document part of classified -

FROM

Chief Engineer, JMI

integrated file. NAME CHECK required prior to individual classification action.

SUBJECT: Admortelgment of receipt of your Bosela Project Report dated 6 March, 1948 and your none to me, dated 8 March 1948.

Receipt of your correspondence as listed above is herewith admovledged. We are sorry to hear that you continue to experience construction delays at the hands of the substantractors. Belows in all categories are disappointing, but those caused by the electrical subcontractor must be most disturbing.

Belaying the Resodn spening date to April 25th was a vice move. It will easily take a full week to set up for operation after the contractors leave. We hope no more delays will be pressed upon you.

The details you gave on the Reseda master ground system were very interesting to me. You should have little difficulty with moise and peer ground, unless the above-ground ground system is too extensive. In such a system, it is well to make more than one connection to actual ground, preferably to or about one of the 2-inch copper ribbens. If another entry to ground is made it would best be done near the farthest-avey-from-ground point on the above-ground syston.

The Dictaphone equipment setup will be somewhat inconvenient for audile. It is unfortunate that Distaphone Corporation is lagging on production of the transcriber companion to the A-M recorder so long. Originally the trans-scriber was to have been out semetime in Merceber, but now the most optimistic date quoted is June, 1948. At the time we erdered the recorders, we were counting on the transcribers being delivered before your spening date, then tentatively scheduled for early 1948. Unfortunately, when using the A-SH recorder for transcribing, the foot control functions only as a start-stop switch. The back speeing will have to be done by hand-setting back the reproducing head with a latch provided for that purpose.

The R.F. Bridge/V.T. Voltmeter item was a typicte error, as far as I can reconstruct what happened. apparently hunded a pencil written form of the two items to a typical for the preparation of a requisition. The girl submitted the requisition for Silver Mill. The error was never caught in time to help you. It may be several menths before you our get delivery of the two items.

The second generator that was shipped to you was obtained by CLL from the Army engineers on a gratic basis. It was, therefore, difficult to get the parts you found missing from the Asmy. The warehouses are in such a state of disorder due to the move from one of them that even if the items you listed were on stock records, it would be a difficult tack to locate them. The efficer in charge of the warehouse is extremely reluctant to take care of anything in the order of old or new business until after the morn from the house to another is completed. The "back to business" date it manufacts but 00

RESILLI

STAT




April 15th. However, on any really important matters, we can sek action out of them - under protect. The inconventance of their way of handling the move is great, but some to be a direct result of trying to do too such with tee few people. Personnal recruitment under security regulations existing is a long and tedious affair.

Let ue know if we can possibly help you.

POR	THE	CHIEF,	MIN
-----	-----	--------	-----

STAT

cc: Chief, Portland Bureau



001020100

İ	FOREIGN	BROADC A	ST IN	SORM	AT'ON	BRAN	СН
50011	r			DATE			
FROM							TO
_ <u></u>	CHIEF						1
	DEPUTY						1
LIAISON OFFICER							1
		EDITORIAL		ON			1
		FIELD DIV					
	CHIEF, SERVICES DIVISION						†
		SPECIAL R					1
		TRATIVE O	FFICER				
	ADMINIS	TDATIVE		<u> </u>			
	FORMATION						
rior riogr	Agument ated fil to indiv	e. NAME	CHECK	regi	PARE RILITED	EPLY [
REMARK	S:				B	w	

STAT

STAT

